

## Shop Engine Fuel And Electrical System Repair, Shelter Mounted

SC: 4940-95-A53  
NSN: 4940-00-209-6228  
LIN: T10446  
TM: 9-4910-410-12

### System Description

Obsolete, no replacement.

**This system is not currently in reset.**

### Reset Type

**Reset Work (Field Level)** - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

### Reset Strategy

n/a

### Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.
- Service SKO IAW TM to 10/20 (annual service) and LO.
- Service prime mover/trailer IAW platform guidance.

### Reset Responsibility

Unit

### Reset Location

This system is not currently in reset.

### **- Contact Information -**

877.4.PMSKOT (877.476.7568)  
[rock-pm-skot@conus.army.mil](mailto:rock-pm-skot@conus.army.mil)